


PDC CURVE



	General	AFa300	AFa400	AFa600
Belt width B		300	400	600
Central radius R		650	650	800
Frame width		326	426	626
Length Y		900=Y or 1150<Y<3000	900=Y or 1150<Y<3000	1050=Y or 1300<Y<3000
Length X		900=X or 1150<X<3000	900=X or 1150<X<3000	1050=X or 1300<X<3000
L1 & L2	$0 \wedge \geq 250$			
h, top of belt	$350 < h < 1500$			

All dimensions in mm

ENDLESS FLEXIBILITY