


PDC U-SHAPE



	General	AFa300	AFa400	AFa600
Belt width B		300	400	600
Central radius R		650	650	800
Frame width		326	426	626
Length Y1 / Y2		900=Y or 1150<Y<3000	900=Y or 1150<Y<3000	1050=Y or 1300<Y<3000
Length X		1300=X or 1550<X<3000	1300=X or 1550<X<3000	1600=X or 1850<X<3000
L1 & L2 & L3	$0 \wedge \geq 250$			
h, top of belt	$350 < h < 1500$			

All dimensions in mm