



PDC S-CURVE



	General	AFa300	AFa400	AFa600
Belt width B		300	400	600
Central radius R		650	650	800
Frame width		326	426	626
Length Y		1300=Y or 1550<Y<5000	1300=Y or 1550<Y<5000	1600=Y or 1850<Y<5000
Length X		1800=X or 2050<X<5000	1800=X or 2050<X<5000	2100=X or 2350<X<5000
L1 & L2 & L3	$0 \wedge \geq 250$			
h, top of belt	$350 < h < 1500$			

All dimensions in mm